## Equipment Technical Bulletin L5000Plus/XL Data Circuit Board Warning

## PROBLEM

Customers have reported damage to their L5000Plus/XL printed circuit boards (both pump driver and Data PCBs) when attempting to install the Data PCB with the power switch on.

## SOLUTION

As with ALL Beta equipment, you must always disconnect power when performing any PCB installation or maintenance.