

Installation Instruction

W6000 84° Nozzle Replacement



BACKGROUND

From April to the end of November, 2002, some of the 84° nozzles we shipped with W6000 were defective. These nozzles will fail to feed, or feed more slowly such that product capsules will not be completely rinsed out.

SOLUTION

In any instance where a *white* 84° nozzle is not feeding adequately, we recommend replacing it with a new nozzle, Item Number 1202348, which is the *blue* 84° nozzle.

Beta Technology will ship free blue nozzles on demand for as many 84° spares and dispensers you purchased during April-November 2002. Please replace the old white nozzles that aren't performing adequately with the blue nozzles, and throw away the white nozzles.

From now on, all 84° nozzles will be blue, so they can easily be discerned from the old nozzles. The old item number white 84° 1201619 has been obsoleted, and whether that number is ordered or the blue 84° 1202348, the blue 1202348 will be shipped. All final assembly item numbers remain the same.

All final assemblies bearing this blue nozzle are factory-tested with water to ensure they have the correct spray pattern prior to shipment. This testing will ensure that any irregularities in spray pattern due to dimensional variance or incorrect assembly are corrected prior to shipment.



Beta Technology
2841 Mission Street
Santa Cruz • CA
U.S.A. • 95060

TEL • 831 • 426 • 0882
TEL • 800 • 858 • 2382
FAX • 831 • 423 • 4573
FAX • 800 • 221 • 8416

TEL (U.S. and Canada) • 800 • 468 • 4893
TEL (outside U.S. and Canada) • 410 • 228 • 1292
Tech Support
sales@beta-technology.com

Beta Technology

4 Finway, Dallow Road
Luton LU1 1TR
United Kingdom

Freephone • 0800 • 052 • 4726
Tel • +44(0) • 1582 • 528600
Fax • +44(0) • 1582 • 528111
Freephone • 0800 • 052 • 4726
VAT REG. NO. BG.354 - 09975 - 44

europa.sales@beta-technology.com

Customer Service

Customer Service

Tech Service

Online Ordering: <http://www.beta-technology.com>

Beta Technology is ISO9001 Certified.