

GX-2004+ ProX

Ultra High Speed Floor Finish



NO INTENTIONALLY ADDED PFAS

FEATURES

- High solids, low odor floor finish
- Extends recoat and stripping cycles

BENEFITS

- Easy to apply and maintain
- Excellent gloss and outstanding durability
- Resists black marks, scratching & dirt embedment

RECOMMENDED USES

For use on all resilient floors.

SPECIFICATIONS

Color : White
Scent : None added
Character : Milky, non-viscous liquid

pH use dilution : 7.7 - 8.7
Phosphorus content : 0.36%
Solids : 25%



IMPORTANT

Read and understand the label and Safety Data Sheet (SDS). These provide a description of hazards, precautions, personal protective equipment, first aid, 24 Hour Emergency lines, storage data and other safe handling information. The SDS is available on our website at www.uschemical.com and is also available by scanning the QR code on the label.

PRODUCT DIRECTIONS

EQUIPMENT TO USE

Appropriate stripping chemicals and equipment, clean mop, mop bucket, burnishing equipment, deep scrubbing equipment, wet floor signs.

DIRECTIONS TO USE

PREPARATION

1. Blockade areas to be stripped or finished. Floors will be very slippery until dry.
2. Strip floors, using a stripper per the instructions on the stripper label.

COATING

1. Apply 3 or more medium coats using a clean finish mop.
2. Allow 30–45 minutes drying time between coats. Temperature, humidity and ventilation may affect drying time. Allow finish to cure for 24 hours before burnishing.

MAINTENANCE

1. Dust mop or sweep.
2. Clean the floor with a mop or an automatic scrubber using the recommended cleaner according to label directions.
3. If desired, dry buff using medium to aggressive pad and 1000– 500 rpm equipment. Ultra-high speed burnish using a medium aggressiveness pad and 2000+ rpm equipment.

RECOATING

1. Dust mop or sweep
2. Clean the floor with a mop or an automatic scrubber using the recommended cleaner according to label directions
3. Blockade area and apply 1-2 uniform coats of finish using a clean mop.
4. Allow finish to cure for 24 hours before burnishing.

REMOVAL

1. Remove using recommended stripper following label directions.

PACKAGING

This product is available in 5 gallon BIB (9299676).