Equipment Technical Bulletin Sierra: Erroneous "Drain Tank" Alarm



OVERVIEW/ISSUE

Sierra unit displays "DRAIN TANK" alarm message even though dish machine's wash tank has just been emptied and refilled.

		R	R		Z_{-}^{\prime}	
	T	R	N	N		

The "Racks Since Last Drain" screen still shows racks counting up and not resetting to "0" after the drain event.

2	K	5	U	<u>Z</u>	[]	×
	2	77	\Box	\Box		П

SOLUTION

- Make sure Sierra unit has constant power during the drain operation. If Sierra has a power interruption during the drain event, the "Racks Since Last Drain" screen will not reset to "0."
- Ensure that at least 20 Beta units (or higher) is programmed for the setpoint in probe mode because a 20 Beta unit differential is needed to qualify the rack reset function.

5	E	Ţ	P		Z I	
8					ΓŪ	\Box



Customer Service

TEL: 831 • 426 • 0882 North America:
TEL: 800 • 858 • 2382 (toll-free in U.S.A.) TEL: 800 • 468 • 4893 (toll-free in U.S.A.)

FAX: 831 • 423 • 4573 FAX: 800 • 221 • 8416

http://www.beta-technology.com

Global Technical Customer Service

TEL: 262 • 631 • 4461 (international) **Europe, Middle East & Africa:** TEL: +1 630 • 513 • 9799

Asia Pacific:

TEL +1 86 21-64180000 x 2520 Japan: TEL: +1 090-6506-5140 Latin America TEL: +1 - 541148428270

Beta Technology is ISO 9001 Certified